


## Burnhope Colliery and Landfill

---

A land quality inspection was carried out at Burnhope Colliery and Landfill site between February and June 2018.

The map below shows the boundary of the inspection area on this former industrial site.



### Why did we inspect this area?

In the past, this area has been the site of a former colliery and landfilling has taken place. There is a risk that the land may have been contaminated with pollutants from these industrial activities.

### Results

The inspection report was received and reviewed in June 2018. The report concluded that in general, there was no concern with the results. We have considered the sub-contractor's recommendations and no further testing is required. The outcome has been reported back to the resident and landowners where sampling was carried out.